



Notes:

1. T1 is wound on a ferrite toroid.
2. T1 Secondary number of turns and wire size were guessed.
3. R2 actually consists of two resistors in parallel.
4. R3 and R4 are on power supply PCB. There may be some additional inside laser head.

Hughes Inverter HeNe Laser PSU 1 (HU-HI1)

Samuel M. Goldwasser		
sam@stdavids.picker.com		
Title		
Hughes Inverter HeNe Laser PSU 1 (HU-HI1)		
Size	Document Number	REV
A	HU-HI1-SCH	1.0
Date:	May 14, 2005	Sheet 1 of 1